

3 Axis Fixture Vise



with the Quick Release Button & Swing Away Arm!

The NEW Quick Access/Swing Away Arm Fixture Vise! With the push of a button, the threaded spindle easily slides in and out. When the job is finished, simply "swing away" the 3rd axis arm for quick and easy part removal!



(A) Quick Acting Screw

(A) Quick Acting Screw

Swing Away Arm (D)

(B) Machined on both sides.

(C) T-Handle



854720 Stand-Off (C)



WAC22, 34, 35D, 45

WAC35-SW (Swing Away Arm)

Part No.	Features	Total Capacity (Sides)	Miter Joints (Ea.Side)	Jaw Height	Jaw Length	T Clearance	Weight	List Price
WAC22	T-Handle (C)	4.41"	2.21"	1.28"	3.54"	1.85"	8.8 lbs.	\$45.00
WAC34	T-Handle (C), Std. Screw	7.5"	3.75"	1.38"	4.80"	2.45"	11.0 lbs.	\$55.00
WAC35D Deluxe	T-Handle (C), Quick Acting Screw (A) Machined on two sides (B)	7.5"	3.75"	1.38"	4.80"	2.45"	11.0 lbs.	\$79.00
WAC35-SW	3-Axis Fixture, Quick Acting Screws (A), Swing Away Arm (D), T-Handle (C)						24.4 lbs.	\$165.00
WAC45	T-Handle (C), Std. Screw	9.5"	4.75"	2.50"	5.32"	3.92"	24.2 lbs.	\$110.00
854720	1/4-20 x 1-1/4" H Stand-offs for increasing space between the jaw and work piece. Applicable to clamp models: WAC35D, 35-SW. (E)						4 oz.	\$1.60

Distributed by:



Web: www.valtrainc.com
Toll-Free: 800-989-5244

© Feb 04